









### Collapse of the Silver Bridge

6 🕅 🤨

At 5:00 PM on December 15, 1967, the Silver Bridge collapsed claiming 46 lives and injuring 9. The Christmas rush applied an extra load to the 39 year old bridge causing a cleavage fracture in one of the "eyebars". This was followed by a ductile fracture near the pin. Unable to support the weight of the entire bridge, the south side chain also snapped. The structure only took about 1 minute to completely fall into the river below. An investigation, led by John Bennett, immediately followed the collapse of the Silver Bridge. The bridge was constructed of carbon steel, which tends to crack. Many cracks were found throughout the bridge among extensive corrosion. The failure resulted from stress corrosion and corrosion fatigue, two concepts which were not known in 1927.(1) It was also found that the flaw could not have been detected, even by today's methods, unless the bridge was taken apart and tested.(1) In addition to the investigation, "the federal government mandated the National Bridge Inspection Standards (NBIS). The new standards required periodic inspection of all the nation's bridges."(3)



to improve bridge health condition.











All six lanes were cleared and made available on November 1, 2001. 11 month after the fracture.

on December 28, 2000, the buckled portion of the bridge was removed without incident.

12 🕅 🧐

the southbound lanes were reopened on February 17, 2001 with one lane of traffic in each direction.

on October 11, 2001, re-opening the bridge to traffic, although only two lanes in each direction were initially available.



http://www.jsonline.com

# Hoan Bridge

Two of the bridge's three support beams had failed and the deck was sagging approximately four feet. The Hoan was immediately closed in both directions with no injury or loss of life while engineers then rushed to the scene to examine the situation and begin mulling over potential solutions. The affected span did not collapse, though, as the third and final support beam kept it from failing, although one source notes "the final girder sustained considerable stress damage until the bridge span was felled two weeks later."

on December 28, 2000, the buckled portion of the bridge was removed without incident.

the southbound lanes were reopened on February 17, 2001 with one lane of traffic in each direction.

on October 11, 2001, Governor Scott McCallum was the first to drive over the newly-repaired northbound lanes at 10:00 am, officially re-opening the bridge to traffic, although only two lanes in each direction were initially available. All six lanes were cleared and made available on November 1, 2001, officially completing the repair work in less than eleven months.

http://www.wisconsinhighways.org/indepth/hoan\_bridge.html







### Fatigue Cases and Retrofit Works in Steel Bridges

#### Causes of fatigue damage

- 1.Weld-defects
- 2. Inappropriate structural details
- 3. Unforeseen stresses and displacements
- 4. Unexpected structural behavior, such as vibration

### Approach to repair and retrofit

Remove the causes of damage Increase fatigue resistance

-----→Design of New Structures

17 🕅 🧐

 Selection of repair and retrofit methods and/or replacement
 Explanation of the causes of damage is indispensable
 There are cases,
 \*immediate measure is necessary
 \*leave the component untouched some years
 Depending on the cause of damage Mechanism of crack initiation and propagation





- two spans continuous girder(45.7 + 45.7m), constructed in 1949. This cracking accident was found in 1981.







wide zone of incomplete penetration was remained in the center part of joints.





• Cracks are arrested in fillet welds between the flange plate and the web plate due to large plastic deformation of weld metal.





• Weld defects of incomplete penetration were discovered in 45 joints out of 388 joints.











#### 32 🕅 🧐

## Collapse of the Songsu Bridge

The disaster struck at 7:38 am, on October 21, 1994, when the bridge was full of vehicles. It was the beginning of the morning rush hour, and many people were riding and driving to work. Suddenly the central part of the famous 120-meter span collapsed and fell into the water. Fortunately, traffic was moving slowly, so most cars could stop within a few seconds. Nonetheless, all the vehicles passing along the part of the bridge that collapsed fell into the Han River. This happened to five vehicles, including a city bus, No. 16. As a result of the disaster 32 people died.

The Songsu Bridge was merely 15 years old when it collapsed.

The bridge was 1,160 meters long, 19.4 meters wide, had four traffic lanes and contained a number of important technical innovations. For example, it was the first welded truss bridge in Korea, and its construction was at the limit of the then technical capabilities available in the country, especially as it included the central 120m span.











































#### 3-3 Fatigue cracks at the cross bracing connection details



53 🕅 🧐

large forces are produced in cross bracing from

- Difference in deflection between main girders caused by vehicle loads
- forced deformation of the upper flanges of plate girders by deflection of the concrete deck in a direction perpendicular to the bridge axis.



- 1. For small cracks : re-welding the crack is done by TIG dressing
- 2. small size fillet weld (possibility of crack from root) : after fillet welding on top of the crack, the toe is finished by TIG or grinding
- 3. When a crack is large : the crack is removed by gouging, fullpenetration welding is performed, with toe finishing done by TIG or grinding.

#### **Repair Work 2**

1. Fatigue cracks have occurred again where stresses produced were large and where cracks had been large.

55 🕅 🤨

- To improving the deformation behavior of the structure, cross bracings and stringers are installed. In this case, 16 mm thick vertical stiffeners are used instead of 10 mm used, their widths were made as large as possible.
- 3. Further, to lower stresses at damaged parts, horizontal members of old cross bracings were removed.





- The sole plate was changed to a longer one and joining with the bottom flange was done using high-strength bolts.
- Cracks which had penetrated into the web, holes were drilled at the tips along with which splicing was done using high strength bolts.
- The holes at the tips of cracks were also tightened with highstrength bolts.
- When cracks of webs are large, welding may also be done.



### 4-2 Fatigue Crack due to Vibration Induced by Wind <sup>59</sup>



- Karman vortex shedding may cause fatigue damage in bridge members.
- fatigue cracks cut the connection plates between the main girder and the vertical suspension members.

M Bridge

The End of Vertical Member In Ranger Type Bridge









# Fatigue crack in beam-column connection of steel pier

- Cracks come out from inside of weld metal.
- From unwelded zone, Lack of fusion, weld crack, or other weld defects



# Cause of fatigue crack

- Intersection of weld line
   →high restraint stress, weld
   flaw (blow hole,slag
   inclusion, weld crack)
- 2. Stress concentration (Geometry, shear lag, bead, notch)
- 3. Inherent Internal Flaw



65 🕅 🥶



Typical Plate Assembling Methods										
WW	WF	FW								
FF	SWW	SFF								
δ zone										





























































	Material property(1)										98 🗖 🧐			
<ul> <li>Sulfur level is not so high, compared to contemporary ste</li> </ul>												steels		
<ul> <li>Some samples show very low RAZ.</li> </ul>														
Chemical compositions														
sa	mple					chemic	al con	npositin(	mass %)				parame	ters
	No.	C	;	Si	Mn	Р	S	Ni	Cu	Cr	Мо	V	Ceq	Pcm
No.1		0.1	6	0.29	1.36	0.012	0.01	2 0.01	7 0.04	0.018	0.012	0.00	0.406	0.242
Ν	No.2		7	0.29	1.36	0.012	0.01	0.01	7 0.04	0.018	0.012	0.00	03 0.416	0.252
No.3		0.1	7	0.29	1.35	0.012	0.00	9 0.01	6 0.04	0.017	0.012	0.00	0.414	0.251
	Z-direction tensile test result													
	sample diamete		meter	0.2% load	d ter		nsile sti	ress	elongat	ion RAZ		break		
No		<b>)</b> .	(	mm)	Load(kN)	) N/mr	n2 L	oad(kN)	N/mm2	(%)	(%)		point	
No.1		1a		9.99	26.81	342	2	27.89	356	3	0	.2	connectio	n
No.11		1b		9.99	28.34	362	2	39.78	508	12		8	A	
No.1		1c		9.99	27.57	352	2	40.13	512	10	1	2	A	
No.2a		2a	1	0.00	26.49	337	39.41		502	18	2	20		_
No.2b		2b	1	0.00	26.39	336	;	40.16	511	10	1	9	<u>A</u>	_
	No.2c 9.99 24.92		318	36.84		4/0	6 1		0	A				
Bolt hole core sample														
► 130 JIS G3199 type C sample														















