





Why was damage extensive in bridges Types of Damage built in recent years? Pre Mid-1990s Typical Chile Bridges Damage resulted from insufficient integrity of pre-cast concrete girder Diaphragm Pre-tension bridges due to absence of diaphragms PC girders Cap beam •Lack of constraint to rotation of deck in skewed bridges After the Mid 1990s influenced by Spanish practice •Damage of piers and foundations in bridges built in the early days •....








Contact of a PC girder to stopper results in failure of lower flange, shear failure of web plate, rupture of deck slabs and connection between deck slab and upper flange




What happened if side stoppers on the top of pier cap were removed in addition to removal of diaphragms?



Vertical restrainers?

- •Resist Uplift?
- •Insufficient to constrain offset of a bridge in the transverse direction



Bridges based on recent practice suffered more damage than bridges based on pre mid-1990s practice

Perquilauquen Bridge Route 5


Very lucky! About to collapse







Lack of constraint to rotation of skewed bridges Skewed bridges tend to rotation under seismic excitation Watanabe, G. and Kawashima, K., Paper No. 789, 13th WCEE, 2004


Skewed bridges which lacked diaphragms and effective side stoppers suffered extensive damage

















Thank you for long contribution! Rio Claro Bridge A 140 years old unreinforced masonry bridge built in 1870







Claro Bridge survived heavy duty for long time


Brittle masonry easy to remove clay soil






 Arch crown was only 3m thick

•It must be very tough to survive heavy traffic






Rupture of Elastomeric Bearing

Las Ballenas Bridge Local Road, Suburbs of Consepcion





A 15 cm tall 60cm by 60cm elastomeric bearing ruptures due to shear at shear strain of about 70%



SUMMARY

•Lack of integrity of a bridge due to absence of diaphragms and effective stopper mechanism in the transverse offset resulted in extensive damage in bridges built after the mid 1990s.

•The above deficiency was particularly intensified in skewed bridges resulted from rotation of a whole bridge.

•In contrast to the bridges built after the mid 1990s with insufficient insight to the seismic effects, the bridges which were built based on the original Chile practice did not suffer extensive damage.

SUMMARY (continued)

•Damage of columns/piers and foundations was not extensive except those in bridges built in the early days. However it is suggested to clarify their strength and deformation capacity if Chile practice moves toward higher connection between decks and substructures for limiting relative displacement.

ACKNOWLEDGEMENTS

Damage investigation of bridges was supported by number of persons. Special appreciation is extended to Ing. Fernandez, M., Ing. Ortega, J.M., Ing. Carracedo, M., Ing. Guzman, M., Ing. Achvrra, S., Ing. Concha, A., Ing. Valdebenito, R. (Ministry of Public Works), Dr. Furuki, M. (JSCE), Dr. Ishii, Y. and Mr. Nguyen, S.H. (CTIE), Dr. Yabe, M. (Chodai), Dr. H.S. Lew (NIST), Dr. Celebi, M. (USGS), Professor Saragoni, G.R. (Univ. Chile), Professor Alvarado, R.V. (Catholica Univ.), Professor Fishinger, M. (Univ. Lubujana), Dr. Muller, J. (Oriental Consultants), Professor Omer, A. (Tokai Univ.) and Ing. Furukawa, K. (Interpreter).