Seismic Design of Urban Infrastructures

Chapter 2 Seismic Damage of Bridges in Past Earthquakes

Kazuhiko Kawashima Tokyo Institute of Technology

2.1 Past Experience What damage did we have in the past?

Stage I: Damage which occurred at the days when seismic effect was not considered or poorly considered in design

1923 Kanto Earthquake (M7.9)



1948 Fukui Earthquake (M7.1)



Collapse of Nakazuno Bridge 1948 Fukui Earthquake



Topological & Geological Conditions

- Being located in the monsoon area, the high-rate erosion developed thick soft sedimentation at the mouth of large rivers in the Asian region.
- Most cities with large population are resting on the thick sedimentation in the Asian region
- Foundation suffered damage resulted from instability of clayey soil and liquefaction and lateral spreading of sandy soils.



Seismic effects were not considered or poorly considered in design

1923 Kanto Earthquake1946 Nankai Earthquake1948 Fukui Earthquake

Tilting, Overturning and Settlement of Foundations

Collapse

As a consequence of the extensive damage in the 1923 Kanto earthquake, seismic design was initiated in 1925

- Elastic static seismic design using 0.2-0.3 seismic coefficients based on the allowable stress design approach
- Construction of massive & rigid piers with large sections started

Stage II (1960-1970s): Importance of considering soil liquefaction and unseating prevention devices was first recognized

1964 Niigata Earthquake

Showa Bridge

Soil Liquefaction

•In old documents there are many descriptions that soil spread out from cracks of ground, and that wells were filled out by sand during earthquakes.

After 1964 Niigata earthquake, this phenomena was first defined as "liquefaction" by a Japanese professor (Professor Mogami), and scientific research was initiated worldwide on the mechanism of liquefaction.

•Fact on ground movement (lateral spreading) was described in damage reports on Niigata earthquake, however research was directed to liquefaction after Niigata earthquake. It was late 1980s when importance on lateral spreading was pointed out by Professor M. Hamada.

This damage resulted in the first development of unseating prevention devices



Unseating Prevention Devices

•Effectiveness of unseating prevention devices was recognized by Japanese engineers who investigated the damage of bridges in 1964 Niigata earthquake.

•They proposed to

 \checkmark extend the seat length

✓ provide connection between adjacent decks

 \checkmark connect the deck to the substructures

•They were incorporated in seismic retrofit first, and then incorporated in the 1971 JRA Guide Specifications on Seismic Design. The practice was then spread worldwide. Stage II: Damage which occurred before the importance of soil liquefaction and unseating prevention devices was recognized

•Consideration to soil liquefaction and unseating prevention devices were not included in seismic design practice prior to 1964

•Excessive relative displacement of decks resulted from soil liquefaction

Collapse

1971 Guide Specifications on Seismic Design of Highway Bridges

• Modified seismic coefficient method which incorporated natural period, soil condition and importance dependence of the seismic coefficient was introduced

• Evaluation of vulnerability for liquefaction was first included

• Unseating prevention devices were first included

Stage-III: Damage resulted from insufficient ductility of columns and strength of bearings

Shear failure of RC Columns

1982 Urakawa-oki Earthquake





Shizunai Bridge

Premature Shear Failure of RC Piers



Premature Shear Failure of Reinforced Concrete Piers Resulting from Insufficient Development Length

Common Design Practice prior to 1985



Loading Experiment at TITech (Sasaki, T. et al., 2005)



Stage-III: Damage resulted from insufficient ductility of columns and strength of bearings

1978 Miyagi-ken-oki Earthquake1982 Urakawa-oki Earthquake1993 Hokkaido-toho-oki EArthquake



Features of Japanese Seismic Design Practice

- A Number of Seismic ExperiencesLarger seismic design force
 - Unseating Prevention Devices
 - Countermeasures for Liquefactions
- Number of Collapsed Bridges
 - ✓ 1923 Kanto EQ M7.9 6
 - ✓ 1946 Nankai EQ M8.1 1
 - ✓ 1948 Fukui EQ M7.3 4
 - ✓ 1964 Niigata EQ M7.5 3
 - ✓ 1978 Miyagi-ken-oki EQ M7.4

2.2 Large Impact of 1995 Kobe, Japan Earthquake







2.2.1 The most extensive damage occurred at a 18-span viaduct. This bridge collapsed due to failure of RC columns resulted from the premature shear failure. Collapse of 18-Span Fuka Hanshin Expressway 1995 Kobe Earthquake

Premature Shear Failure of RC Columns Resulted from Insufficient Development Length







Collapse of a 18-span viaduct in the 1995 Kobe Earthquake





Collapse of a 18-span viaduct in the 1995 Kobe Earthquake





Enhancement of Ductility Capacity



2.2.2 Shear Failure of RC Columns

Shear Failure



Shear Failure



2.2.3 Failure of Steel Piers







Progress of Failure of Steel Columns (continued)





2.2.4 Damage of Foundations

Damage of foundations was less, but none



2.2.5 Extensive Damage of Bearings







Vulnerable Steel Pin & Roller Bearings



Vulnerable Steel Roller Bearings

Rollers have moved out

Stoppers have gone



Change of Design Practice on Bearings after 1995 Kobe Earthquake

•Damage of bearings (steel bearings) was an issue of discussion at every time when a damaging earthquake occurred.

•However there was always an argument that bearing damage was a fuse to restrict extensive damage at the substructures. As a consequence, only minor upgrading had been adopted for design of bearings.

•However it was so obvious that bearing damage was not a fuse for restricting damage of substructures, but it was one of the main causes of the extensive damage in the 1995 Kobe earthquake.

Consequence of the 1995 Kobe Earthquake (cont.)

- •It was recommended in the 1995 & 1996 codes that elastomeric bearings including LRB and HDR should be used.
- •Steel bearings have the following deficiencies:
 - \checkmark Insufficient strength and weak for shock
 - ✓ Structures with insufficient lateral and vertical capacity
 - ✓ Insufficient lengnth of movement

•As a consequence, about 98% of the total bearing was steel bearing before 1995, but 90% is now elastomeric bearings.

2.2.6 Damage of Unseating Prevention Devices



2.2.7 Residual Tilt of Columns

First Provision to Residual Tilt of Piers

•A new provision was introduced for limiting residual tilt of columns after the 1995 Kobe earthquake. This was the first provision for the residual tilt.

•Residual displacement response spectra were used to formulate the provision as:

 $u_R < u_{Ra}$ - Design residual displacement

$$u_R = c_R \cdot u_R \max = c_R (\mu_r - 1)(1 - r)u_y$$
$$u_{Ra} = \frac{1}{100} H \longleftarrow Column height$$

2.2.7 Summary of the 1995 Kobe Earthquake

What were lessons?

Experience of the 1995 Kobe Earthquake

Past damage occurred at foundations & Piers/Columns

Construction of Massive & Stiff Foundations & Piers with Large Sections

Restrictions of Space under Bridges

Construction of Slender RC and Steel Columns

Extended the Past Design Practice to Slender RC and Steel Columns

Cause of Damage of Bridges in 1995 Kobe Earthquake

•Destructive near field ground motions

•Insufficient strength & ductility of columns, bearings and unseating prevention devices.

Have good insight on the damage & bridge behavior under extensive ground motions

•Seeing is believing.

- •We tend not to believe what we have not yet seen.
- •We should have a good insight on what could happen.

Number of Pages related to Seismic Design of Highway Bridges in Japan

About a half pages was references

What are the research targets in the next 10 years?

•Are bridges safe as a system to ensure the safety of public in the urban areas?

•What are the next type damage?

•Are the current seismic performance goal that bridge should not collapse during an extensive earthquake acceptable to the public?

What are the concern of the public?

