

4th Lecture


Design Examples

Example 12.8 (Slow Stable Process Zeros) (pp.362 to 364)

Example 12.9 (Fast Stable Process Poles) (pp.364 to 365)

Example 12.10 (Design Rules for Pole Placement) (pp.366 to 368)

[Ex. 12.8] Vehicle steering



input: $u = \delta$ output: y
state: $x = (y, \theta)$

State equation : Plant model (§ 8.3)

$$\frac{dx}{dt} = Ax + Bu, \quad y = Cx + Du$$
$$A = \begin{bmatrix} 0 & 1 \\ 0 & 0 \end{bmatrix} \quad B = \begin{bmatrix} \gamma \\ 1 \end{bmatrix} \quad C = \begin{bmatrix} 1 & 0 \end{bmatrix} \quad D = 0$$

Transfer function

$$P(s) = C(sI - A)^{-1}B + D = \frac{\gamma s + 1}{s^2}$$

$\gamma = 0.5$

(Ex. 2.8, 5.12, 7.3, 7.4, 8.6)




Fig. 2.16 Vehicle steering dynamics

[Ex. 12.8] Vehicle steering

Controller

Observer

$$\frac{d\hat{x}}{dt} = A\hat{x} + Bu + L(y - C\hat{x})$$

State feedback

$$u = -K\hat{x} + k_r r$$

Closed loop system $\tilde{x} = x - \hat{x}$

$$\frac{d}{dt} \begin{bmatrix} x \\ \tilde{x} \end{bmatrix} = \begin{bmatrix} A - BK & BK \\ 0 & A - LC \end{bmatrix} \begin{bmatrix} x \\ \tilde{x} \end{bmatrix} + \begin{bmatrix} Bk_r \\ 0 \end{bmatrix} r$$
$$y = \begin{bmatrix} C & 0 \end{bmatrix} \begin{bmatrix} x \\ \tilde{x} \end{bmatrix}$$

$$\lambda(s) = \det(sI - A + BK) \det(sI - A + LC) \quad \text{Separation Principle}$$




Fig. 8.9 Block diagram for a steering control system

[Ex. 12.8] Vehicle steering Pole Placement

State feedback gain

$$\det(sI - A + BK) = s^2 + (\gamma k_1 + k_2)s + k_1$$
$$= s^2 + 2\zeta_c \omega_c s + \omega_c^2$$
$$k_1 = \omega_c^2 \quad k_2 = 2\zeta_c \omega_c - \gamma \omega_c^2$$

Observer gain


$$\det(sI - A + LC) = s^2 + l_1 s + l_2$$
$$= s^2 + 2\zeta_o \omega_o s + \omega_o^2$$
$$l_1 = 2\zeta_o \omega_o \quad l_2 = \omega_o^2$$

Faster close loop system


$$\begin{cases} \omega_c = 10 & \omega_o = 20 \\ \zeta_c = 0.707 & \zeta_o = 0.707 \end{cases}$$
$$\begin{cases} -7.07 \pm 7.07i & -14.14 \pm 14.14i \end{cases}$$

Should be GOOD?

$$\begin{cases} k_1 = 100 & l_1 = 28.28 \\ k_2 = -35.86 & l_2 = 400 \end{cases}$$



[Ex. 12.8] Vehicle steering




The controller achieves a good control performance, doesn't it?

[Ex. 12.8] Vehicle steering

$$\begin{cases} \omega_c = 10 & \omega_o = 20 \\ \zeta_c = 0.707 & \zeta_o = 0.707 \end{cases}$$
$$\begin{cases} -7.07 \pm 7.07i & -14.14 \pm 14.14i \end{cases}$$


Nominal $V = 1$
Variation $0.95 \leq V \leq 1.05$



Oops... both performance and robust stability are poor !

[Ex. 12.8] Slow Stable Process Zeros


What happens ?



Process (from u to y)

$$P(s) = C(sI - A)^{-1}B + D = \frac{\gamma s + 1}{s^2} = \frac{0.5s + 1}{s^2}$$


Pole : $p = 0, 0$
Zero : $z = -2$



Controller (from y to u) (§ 8.3)

$$C(s) = \frac{KG_{xy}(s)}{1 + KG_{xu}(s)} = \frac{-11516s + 40000}{s^2 + 42.4s + 6657.9}$$

Pole : $p = -21 \pm 79i$
Zero : $z = 3.47$



[Ex. 12.8] Slow Stable Process Zeros

$$T = \frac{PC}{1 + PC} = \frac{n_p n_c}{d_p d_c + n_p n_c}$$


$P = \frac{n_p}{d_p}, C = \frac{n_c}{d_c}$

T has the poles of closed-loop system and its zeros are given by zeros of the process and controller

Process (from u to y)

$$P(s) = \frac{0.5s + 1}{s^2} \leftarrow n_p$$

Pole : $p = 0, 0$
Zero : $z = -2$



Controller (from y to u)

$$C(s) = \frac{-11516s + 40000}{s^2 + 42.4s + 6657.9} \leftarrow n_c$$


Pole : $p = -21 \pm 79i$
Zero : $z = 3.47$



Closed-loop (from r to y)


$$T(s) = \frac{-5758(s+2)(s-3.47)}{(s^2 + 14.14s + 100)(s^2 + 28s + 400)}$$

Pole : $d_p d_c + n_p n_c = 0$
 $p = -7.07 \pm 7.07i$
 $-14.14 \pm 14.14i$
Zero : $z = -2, 3.47$



[Ex. 12.8] Slow Stable Process Zeros

$$T = \frac{PC}{1 + PC} = \frac{n_p n_c}{d_p d_c + n_p n_c}$$



The magnitude of the peak depends on the ratio of the zeros and the poles of the transfer function.


assign a closed loop pole close to the slow process zero

[Ex. 12.8] Slow Stable Process Zeros

Process


$$P(s) = \frac{0.5s + 1}{s^2}$$

Pole : $p = 0, 0$
Zero : $z = -2$
*process stable zero $z = -2$




Faster close loop system

$$\left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 0.707 & \zeta_o = 0.707 \end{array} \right. \rightarrow \begin{array}{l} \text{closed loop pole} \\ -7.07 \pm 7.07i \\ -14.14 \pm 14.14i \end{array}$$



Assign a closed loop pole close to the slow process zero.

$$\left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 2.6 & \zeta_o = 0.707 \end{array} \right. \rightarrow \begin{array}{l} \text{closed loop pole} \\ -2, -50 \\ -14.14 \pm 14.14i \end{array}$$
$$(\det(sI - A + BK) = s^2 + 2 \cdot 2.6 \cdot 10s + 10^2) = (s + 2)(s + 50)$$




[Ex. 12.8] Slow Stable Process Zeros

Process: $P(s) = \frac{0.5s + 1}{s^2}$

$$\left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 2.6 & \zeta_o = 0.707 \end{array} \right. \rightarrow C(s) = \frac{3628(s + 11.02)}{(s + 2)(s + 78.28)}$$



*process stable zero



$$T(s) \approx \frac{1814(s + 11)(s + 2)}{(s + 2)(s + 50)(s^2 + 28s + 400)}$$

Controller


$$\left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 2.6 & \zeta_o = 0.707 \end{array} \right. \rightarrow \begin{array}{l} \text{closed loop pole} \\ -2, -50 \\ -14.14 \pm 14.14i \end{array}$$



Assign a closed loop pole close to the slow process zero

[Ex. 12.8] Slow Stable Process Zeros

$$\left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 0.707 & \zeta_o = 0.707 \end{array} \right. \quad \left\{ \begin{array}{ll} \omega_c = 10 & \omega_0 = 20 \\ \zeta_c = 2.6 & \zeta_o = 0.707 \end{array} \right.$$



[Ex. 12.9] Fast Stable Process Poles

Process
 $P(s) = \frac{b}{s+a}$
Pole : $p = -a$

PI controller
 $C(s) = \frac{k_p s + k_i}{s}$
Pole : $p = 0$
Zero : $z = -k_i / k_p$


Loop transfer function
 $L(s) = \frac{b(k_p s + k_i)}{s(s+a)}$

Closed loop characteristic polynomial
 $s(s+a) + b(k_p s + k_i) = s^2 + (a + bk_p)s + k_i b$
desired closed loop poles: $-p_1 - p_2, s^2 + (p_1 + p_2)s + p_1 p_2$
 $k_p = \frac{p_1 + p_2 - a}{b}, k_i = \frac{p_1 p_2}{b}$

Complementary sensitivity
 $T(s) = \frac{(p_1 + p_2 - a)s + p_1 p_2}{(s + p_1)(s + p_2)}$

Sensitivity
 $S(s) = \frac{s(s+a)}{(s + p_1)(s + p_2)}$

assume $p_1 < p_2 \ll a$



[Ex. 12.9] Fast Stable Process Poles

assume $p_1 < p_2 \ll a$

$S(s) = \frac{s(s+a)}{(s + p_1)(s + p_2)}$




Fig. 12.13

Choose one closed loop pole equal to the process pole
 $p_2 = a$

[Ex. 12.9] Fast Stable Process Poles

Process
 $P(s) = \frac{b}{s+a}$
Pole : $p = -a$


PI controller $C(s) = \frac{k_p s + k_i}{s}$
 $k_p = \frac{p_1 + p_2 - a}{b}, k_i = \frac{p_1 p_2}{b}$
Pole : $p = 0$
Zero : $z = -k_i / k_p$

Sensitivity
 $S(s) = \frac{s(s+a)}{(s + p_1)(s + p_2)}$

assume $p_1 < p_2 \ll a$

Choose one closed loop pole equal to the process pole.
 $p_2 = a$
 $k_p = \frac{p_1}{b}, k_i = \frac{ap_1}{b}$
 $C(s) = \frac{k_p(s+a)}{s}$
Pole : $p = 0$
Zero : $z = -a$

$L(s) = \frac{b}{s+a} \cdot \frac{k_p(s+a)}{s} = \frac{bk_p}{s}$
 $S(s) = \frac{s}{s + bk_p}, T(s) = \frac{bk_p}{s + bk_p}$



The fast process pole is canceled by a controller zero

[Ex. 12.9] Fast Stable Process Poles


Process
 $P(s) = \frac{b}{s+a}$
Pole : $p = -a$


PI controller $C(s) = \frac{k_p(s+a)}{s}$
 $k_p = \frac{p_1}{b}, k_i = \frac{ap_1}{b}$
Pole : $p = 0$
Zero : $z = -a$

Sensitivity
 $S(s) = \frac{s(s+a)}{(s + p_1)(s + p_2)}$

assume $p_1 < p_2 \ll a$

$p_2 = a$
 $S(s) = \frac{s}{s + bk_p}$





Choose one closed loop pole equal to the process pole


Recap. [Ex. 11.7] Zero in the right half-plane


All-pass system with a RHP zero
 $P_{ap}(s) = \frac{z-s}{z+s}, z > 0$

Phase lag of the all-pass system
 $-\arg P_{ap}(j\omega) = -\{\arg(z - j\omega) - \arg(z + j\omega)\}$
 $= 2 \arctan \frac{\omega}{z}$

gain crossover frequency inequality
 $-\arg P_{ap}(j\omega_{gc}) \leq \pi - \varphi_m + n_{gc} \frac{\pi}{2} =: \varphi_l \quad (11.15)$

Bound on the crossover frequency ω_{gc}
 $\omega_{gc} < z \tan(\varphi_l / 2) \quad (11.16)$






Recap. [Ex. 11.8] Pole in the right half-plane


All-pass system with a RHP pole
 $P_{ap}(s) = \frac{s+p}{s-p}, p > 0$

Phase lag of the all-pass system
 $-\arg P_{ap}(j\omega) = -\{\arg(p + j\omega) - \arg(j\omega - p)\}$
 $= 2 \arctan \frac{p}{\omega}$

gain crossover frequency inequality
 $-\arg P_{ap}(j\omega_{gc}) \leq \pi - \varphi_m + n_{gc} \frac{\pi}{2} =: \varphi_l \quad (11.15)$



Bound on the crossover frequency ω_{gc}
 $\omega_{gc} > \frac{p}{\tan(\varphi_l / 2)} \quad (11.17)$





Design Rules for Pole Placement

- **Slow stable process zeros:** should be cancelled by the controller poles.
- **Fast stable process poles:** should be cancelled by the controller zeros
- **Slow unstable process zeros:** achievable ω_{gc} must be smaller than the slowest unstable process zero.
- **Fast unstable process poles:** the gain crossover frequency must be sufficiently large.



[Ex. 12.10] Nanopositioning system for an atomic force microscope (Ex. 9.9)

$$P(s) = \frac{a^2}{s^2 + 2\zeta as + a^2} \quad C(s) = \frac{k_i s^2 + 2\zeta as + a^2}{s}$$
$$L(s) = \frac{0.5}{s} \rightarrow S(s) = \frac{s}{s + 0.5} \quad T(s) = \frac{0.5}{s + 0.5}$$

Gang of Four




Fig. 12.14

[Ex. 12.10] Nanopositioning system for an atomic force microscope




Fig. 12.14

[Ex. 12.10] Nanopositioning system for an atomic force microscope

$$C(s) = \frac{k_d s^2 + k_p s + k_i}{s} \quad P(s) = \frac{a^2}{s^2 + 2\zeta as + a^2}$$

Loop transfer function

$$L(s) = \frac{a^2 (k_d s^2 + k_p s + k_i)}{s (s^2 + 2\zeta as + a^2)}$$

Characteristic polynomial

$$s^3 + (a^2 k_d + 2\zeta a) s^2 + (k_p + 1) a^2 s + k_i a^2$$


general third-order parameterized polynomial


$$s^3 + (\alpha_0 + 2\zeta) \omega_0 s^2 + (1 + 2\alpha_0 \zeta) \omega_0^2 s + \alpha_0 \omega_0^3$$

α_0, ζ : relative configuration of the poles
 ω_0 : magnitudes of the poles

$$k_p = \frac{(1 + 2\alpha_0 \zeta) \omega_0^2}{a^2} - 1, \quad k_i = \frac{\alpha_0 \omega_0^3}{a^2}, \quad k_d = \frac{(\alpha_0 + 2\zeta) \omega_0 - 2\zeta a}{a^2}$$

[Ex. 12.10] Nanopositioning system for an atomic force microscope





4th Lecture

Design Examples

Example 12.8 (Slow Stable Process Zeros) (pp.362 to 364)

Example 12.9 (Fast Stable Process Poles) (pp.364 to 365)

Example 12.10 (Design Rules for Pole Placement)
(pp.366 to 368)

Next: 5th Lecture

11 Frequency Domain Design

11.5 Fundamental Limitations (pp.331 to 340)

Keyword : Right Half-Plane Poles and Zeros
Gain Crossover Frequency Inequality