Nuclear Reactor Theory I Lecture Note (6)
- One-speed diffusion theory of a nuclear reactor (2) -

Toru Obara

Tokyo Institute of Technology

5.2 The critical condition for general bare geometries

Considering a bare reactor of uniform composition surrounded by a free surface characterized by vacuum boundary conditions.

If the reactor is critical then the neutron flux must satisfy the steady-state diffusion equation.

$$- D\nabla^2 \phi + \Sigma_a \phi(\mathbf{r}) = \nu \Sigma_f \phi(\mathbf{r}) \qquad \cdots (1)$$

boundary condition : $\phi(\tilde{\mathbf{r}}_s) = 0$ $\tilde{\mathbf{r}}_s$: extrapolated boundary

Dividing Eq.(1) by -D,

$$\nabla^2 \phi + \left(\frac{\nu \Sigma_f - \Sigma_a}{D}\right) \phi(\mathbf{r}) = 0 \qquad \cdots (2)$$

boundary condition : $\phi(\tilde{\mathbf{r}}_s) = 0$

i.e.
$$\nabla^2 \phi + \left(\frac{k_{\infty} - 1}{L^2}\right) \phi(\mathbf{r}) = 0$$
 ... (3)

boundary condition : $\phi(\tilde{\mathbf{r}}_s) = 0$

This equation is identical to that which generates the special eigenfunctions for this geometry.

$$\nabla^2 \psi_n + B_n^2 \psi_n(\mathbf{r}) = 0 \qquad \cdots (4)$$

boundary condition : $\psi(\tilde{\mathbf{r}}_S) = 0$

The requirement that the reactor is critical is the same as that for slab reactor,

$$B_{\rm m}^{2} \equiv \left(\frac{\nu \Sigma_{\rm f} - \Sigma_{\rm a}}{D}\right) = B_{1}^{2} \equiv B_{\rm g}^{2} \qquad \cdots (5)$$

The critical neutron flux distribution $\phi(\mathbf{r})$ is given by the fundamental eigenfunction $\psi_1(\mathbf{r})$.

Geometric buckling and flux profile for various bare core

Bare core geometry	Geometric buckling	Flux profile
Slab (thickness:	$(\pi)^2$	$\cos \frac{\pi x}{3}$
a)	$\left(\frac{\pi}{\tilde{a}}\right)^2$	ã
Sphere (radius:	$\left(\frac{\pi}{\overline{p}}\right)^2$	$r^{-1}\sin\left(\frac{\pi r}{\overline{b}}\right)$
R)	$\left\langle \overline{\widetilde{\mathbb{R}}} ight angle$	$1 \sin(\overline{\widetilde{R}})$
Rectangular	$\left(\frac{\pi}{\tilde{a}}\right)^2 + \left(\frac{\pi}{\tilde{b}}\right)^2 + \left(\frac{\pi}{\tilde{c}}\right)^2$	$\cos\left(\frac{\pi x}{\tilde{a}}\right)\cos\left(\frac{\pi x}{\tilde{b}}\right)\cos\left(\frac{\pi x}{\tilde{c}}\right)$
parallelepiped	$(\frac{\overline{a}}{\tilde{a}}) + (\frac{\overline{b}}{\tilde{b}}) + (\frac{\overline{c}}{\tilde{c}})$	$\tilde{a} = \frac{1}{\tilde{b}} = \frac{1}{\tilde{b}} = \frac{1}{\tilde{c}}$

Eq.(4) will provide us with flux shape only in critical reactor.

The magnitude of neutron flux shall be determined by the total power P generated by the core.

$$P = \int_{V} d^{3}r w_{f} \Sigma_{f} \phi(\mathbf{r}) \qquad \cdots (6)$$

w_f: energy produced per fission event

5.3 Reflected reactor geometries

We consider a slab reactor with reflectors of nonmultiplying material of thickness of to the both side of the core.

Time-independent diffusion equation $(x \ge 0)$

Core:
$$-D^{C} \frac{d^{2} \phi^{C}}{dx^{2}} + \left(\Sigma_{a}^{C} - \nu \Sigma_{f}^{C}\right) \phi^{C}(x) = 0, \qquad 0 \le x \le \frac{a}{2} \qquad \cdots (7)$$

Reflector:
$$-D^R \frac{d^2 \phi^R}{dx^2} + \Sigma_a^R \phi^R(x) = 0, \qquad \frac{a}{2} \le x \le \frac{a}{2} + \tilde{b} \qquad \cdots (8)$$

Boundary conditions

(a)
$$\phi^{C}\left(\frac{a}{2}\right) = \phi^{R}\left(\frac{a}{2}\right)$$

(b) $J^{C}\left(\frac{a}{2}\right) = J^{R}\left(\frac{a}{2}\right)$... (9)

(c)
$$\phi^{R}\left(\frac{a}{2} + \tilde{b}\right) = 0$$

General solution in the core (symmetric solution)

$$\Phi^{C}(x) = A^{C}\cos B_{m}^{C}x$$

where,
$$B_m^{C^2} \equiv \frac{\nu \Sigma_f^C - \Sigma_a^C}{D^C}$$
 ... (10)

Solution in reflector which satisfies boundary condition (c)

$$\phi^{R}(x) = A^{R} \sinh \left[\frac{\frac{a}{2} + \tilde{b} - x}{L^{R}} \right] \qquad \cdots (11)$$

where,
$$L^R = \sqrt{\frac{D^R}{\Sigma_a^R}}$$

By applying interface boundary conditions (a) and (b),

$$A^{C}\cos\left(\frac{B_{m}^{C}a}{2}\right) = A^{R}\sinh\left(\frac{\tilde{b}}{L^{R}}\right) \qquad \cdots (12)$$

$$D^{C}B_{m}^{C}A_{c}\sin\left(\frac{B_{m}^{C}a}{2}\right) = \frac{D^{R}}{L^{R}}A^{R}\cosh\left(\frac{\tilde{b}}{L^{R}}\right) \qquad \cdots (13)$$

Dividing Eq.(13) by Eq.(12),

$$D^{C}B_{m}^{C}\tan\left(\frac{B_{m}^{C}a}{2}\right) = \frac{D^{R}}{L^{R}}\coth\left(\frac{\tilde{b}}{L^{R}}\right) \qquad \cdots (14)$$

This equation is the reactor critical condition.

(cf.
$$B_m^2 = B_g^2$$
 in bare core)

Rewrite Eq.(14) as

$$\left(\frac{B_{\rm m}^{\rm C}a}{2}\right)\tan\left(\frac{B_{\rm m}^{\rm C}a}{2}\right) = \frac{D^{\rm R}a}{2D^{\rm C}L^{\rm R}}\coth\left(\frac{\tilde{b}}{L^{\rm R}}\right) \qquad \cdots (15)$$

$$\frac{B_m^C a}{2} < \frac{\pi}{2} \quad \text{or} \quad {B_m^C}^2 < \left(\frac{\pi}{a}\right)^2$$

$$\begin{bmatrix} \text{In bare (unreflected) core} \\ {B_m}^2 = \left(\frac{\pi}{\tilde{a}}\right)^2 \end{bmatrix}$$

It is conventional to define the difference between bare and reflected core dimensions as the reflector savings $\,\delta\,$:

$$\delta = [a(bare) - a(reflected)]/2 \qquad \cdots (16)$$

Ex. The reflector savings for the slab core

$$\delta = \frac{1}{B_{m}^{C}} tan^{-1} \left[\frac{D^{C} B_{m}^{C} L^{R}}{D^{R}} tanh \left(\frac{\tilde{b}}{L^{R}} \right) \right] \qquad \cdots (17)$$

For the thick reflector $b \gg L^R$

$$\delta \cong \frac{D^{C}}{D^{R}}L^{R} \qquad \cdots (18)$$

- 5.4 Reactor criticality calculations
- (1) General procedure to determine geometries and material composition of critical reactors

Diffusion equation

$$-\nabla D\nabla \varphi + \Sigma_a \varphi(\mathbf{r}) = \nu \Sigma_f \varphi(\mathbf{r}) \qquad \cdots (19)$$
 (no solutions in general unless the reactor is critical) boundary condition

$$\phi(\tilde{\mathbf{r}}_s) = 0$$

We introduce on arbitrary parameter "k" into the equation.

$$-\nabla D\nabla \phi + \Sigma_{a}\phi(\mathbf{r}) = \frac{1}{k}\nu\Sigma_{f}\phi(\mathbf{r}) \qquad \cdots (20)$$

Picking up a core size and composition and solve the equation while determining k. (eigenvalue problem)

k: multiplication eigenvalue

(2) Solution of eigenvalue problem by power method

Rewriting Eq.(20) in operator notation

$$\mathsf{M}\boldsymbol{\varphi} = \frac{1}{\mathsf{k}}\mathsf{F}\boldsymbol{\varphi} \qquad \cdots (21)$$

where,
$$M \equiv -\nabla D(\mathbf{r})\nabla + \Sigma_a(\mathbf{r}) \equiv Destruction$$
 operator (leakage plus absorption) $F \equiv \nu \Sigma_f(\mathbf{r}) \equiv Production$ operator (fission)

Assuming the estimate $\phi^{(n)}$ and $k^{(n)}$ are given.

Estimate of fission source

$$S^{(n)} = F \phi^{(n)} \qquad \cdots (22)$$

We can iteratively solve for an improved source estimates $S^{(n+1)}$ from an earlier estimate $S^{(n)}$ by solving

$$M\Phi^{(n+1)} = \frac{1}{k^{(n)}} S^{(n)} \qquad \cdots (23)$$

for $\phi^{(n+1)}$ and then computing

$$S^{(n+1)} = F\varphi^{(n+1)} \qquad \cdots (24)$$

as n becomes large, $\phi^{(n+1)}$ will converge to the true eigenfunction $\phi(\mathbf{r})$ that satisfies Eq.(21) with the eigenvalue

$$\mathsf{M}\phi^{(n+1)} \cong \frac{1}{k^{(n+1)}} \mathsf{F}\phi^{(n+1)}$$
 ... (25)

If we integrate Eq.(25) overall space, we should be able to obtain a resonance estimate for $\mathbf{k}^{(n+1)}$ as

$$k^{(n+1)} \cong \frac{\int d^3 r F \phi^{(n+1)}}{\int d^3 r M \phi^{(n+1)}} \qquad \cdots (26)$$

From Eq.(23), Eq.(24)

$$k^{(n+1)} \cong \frac{\int d^3r S^{(n+1)}(\mathbf{r})}{\frac{1}{k^{(n)}} \int d^3r S^{(n)}(\mathbf{r})}$$
effective fission sources
that generate $S^{(n+1)}$

This shows the eigenvalue, k in Eq.(21) is the same as the effective multiplication factor, that is the ratio of the number of neutrons in two consecutive fission generations in the reactor.

In $k\neq 1$, to make the reactor critical, we can change the reactor size and composition and repeat the calculation.